

## ABSOLUTE GAUGES

Used for measurement of pressure where the barometric pressure must not influence the measurement accuracy. This is achieved by fully evacuating the capsule and sealing the case so that absolute pressure measurement is made against a reference of absolute zero. The dial is usually scaled in torr and / or millibar.

These instruments are built to special order to customer specification. Please contact us for further information or quotation.



**cewal** UK LTD

Unit 4C • Woodhall Business Park • Sudbury • Suffolk • CO10 1WH

Tel: +44 (0) 1787 882038 • Fax: +44 (0) 1787 882039

Email: [info@cewal.co.uk](mailto:info@cewal.co.uk) • Website: [www.cewal.co.uk](http://www.cewal.co.uk)