

LOAD GAUGES

Special dials can be supplied when weight or force needs to be measured rather than pressure. These are frequently used on hydraulic presses and the area of the ram must be supplied in order to calculate the pressure range and calibrate the dial. Dials can be marked in many different scales for example imperial or metric weights.

These instruments are built to special order to customer specification. Please contact us for further information or quotation.



cewal UK LTD

Unit 4C • Woodhall Business Park • Sudbury • Suffolk • CO10 1WH

Tel: +44 (0) 1787 882038 • Fax: +44 (0) 1787 882039

Email: info@cewal.co.uk • Website: www.cewal.co.uk